

Test Report

No. 10117392A/08

Date: March 7, 2008

Page 1 of 2


Alpha Metals Singapore
14 Tuas Avenue 10
Singapore 639138

The following sample(s) was/were submitted and identified by/on behalf of the client as:

Product Description : SMT plus core flux
Sample Receiving Date : 05 March 2008
Testing Period : 06 March 2008 to 07 March 2008

Test Result(s) : Please refer to next page(s).

Signed for and on behalf of
SGS Testing & Control Services Singapore Pte Ltd



Y.C. Tham
Laboratory Manager

Test Location: 26 Ayer Rajah Crescent, #07-07, Singapore 139944

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. *Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only. This document cannot be reproduced except in full, without prior approval of the Company.*

Test Report

No. 10117392A/08

Date: March 7, 2008

Page 2 of 2

Test Result(s):

Product Description : SMT plus core flux

Test Item(s)	Unit	Method	MDL	Result
Halogen				
Halogen - Bromine (Br) CAS No. 007726-95-6	mg/kg	With reference to BS EN14582. Analysis was performed by IC.	50	n.d.
Halogen - Chlorine (Cl) CAS No. 007782-50-5	mg/kg	With reference to BS EN14582. Analysis was performed by IC.	50	n.d.

Note: (1) mg/kg = ppm
 (2) n.d.= Not Detected
 (3) MDL = Method Detection Limit

Remarks: Sample received was totally dissolved by preconditioning & destroyed after the analysis.
 Lab Analyst(s): Jenny Yip

Sample photo:



SGS authenticate the photo on original report only

End of Report

Test Location: 26 Ayer Rajah Crescent, #07-07, Singapore 139944

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/terms_and_conditions.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. *Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only. This document cannot be reproduced except in full, without prior approval of the Company.*